














KWADRO PLUS 40 1D




		P0	P1	X
				
		ø 5	ø 8	
		x 22	x 4	x 2
H-160	K1	KTL	P2	P11
				
L=160mm	M4x20		ø 18	
x 1	x 2	x 12	x 4	x 2



01.














02.







03.




04.




05.



06.



06.



07.

